

POWER PROBE®

PPFUSE

FUSE MONITOR

Top displays either inactive, active, or open when measuring across a fuse for quick diagnosis



- Accurately measures current without removing the fuse
- Perfect for locating circuits with a parasitic draw
- Ability to read Maxi, Mini, & ATC fuses up to 80A

**PAIRS PERFECTLY
WITH THE
DRAW MONITOR!**



Live current reading display (A)

Screen hold

Screen brightness

USB-C rechargeable

Flashlight

Replaceable tips

Accuracy

Down to 1mA

Fuses

Maxi, Mini,
ATC

Recharge

USB-C