

Automotive Current Tester

Specifications

Fuse Type	LCD Display Resolution	Measuring Range	Accuracy
80A /Max-Blade	0.1A	80A	$\pm(2.0\% \text{ reading} + 4 \text{ digits})$

Current	: 0A to 80Amax
Operating Temperature	: 0°C to 50°C(32°F to 122°F)
Storage Temperature	: -20°C to 60°C(-4°F to 140°F)
Relative Humidity	: <70% operating, <80% storage
Operating Altitude	: 7000ft (2000 meters) maximum



Size: 112x45x33mm

Weight: 165g

