
RMAX-IMP12A

1/2" Angle Impact Wrench



| Index No. | Parts No. | Description | Index No. | Parts No. | Description | |
|--------------|----------------|---------------------------------|--------------|--------------|------------------|----------------|
| 1 | 41-401001-0002 | Motor Housing | 24 | 40145 | Steel Ball | (1/8") |
| 2 | 70102 | Spring Pin (2.5x2 | 0) 25 | 41-401026 | Anvil Bushing | |
| 3 | 41-401003 | Air Inlet | 26 | 41-401254 | Oil Cap | (1/8") |
| 4 | 41-401004 | Throttle Lever | 27 | 51217 | Spring Pin | (2x4) |
| 5 | 41-401005 | Pin | 28 | OR03708106 | O-Ring | (37.8x1.6) |
| 6 | 41-401006 | Reverse Valve | 29 | OR03407108 | O-Ring | (34.65x1.78) |
| 7 | 41-401007 | Exhaust Diffuser | 30 | 41-401030 | Screw (4) | (M5x15L) |
| 8 | OR01000100 | O-Ring (10) | 1) 31 | 41-401031 | Washer | |
| 9 | 41-401009 | Handle | 32 | 41-401032 | Clamp Nut | |
| 10. | 206002 | Inverted Retaining Ring (ISTW-3 | 0) 33 | 41-401008-21 | Hammer Cage | |
| 11 | 41-401034 | Gasket | 34 | 41-401211 | Hammer | |
| 12 | 41-401020 | Rear Cover | 35 | 41-401017-21 | Hammer Pin (2) | (5.1x25) |
| 13 | 040120 | Ball Bearing (EB | 3) | 43-401002-21 | Anvil | (R-Type 1/2") |
| 14 | OR00905105 | O-Ring (2) (9.5x1 | 5) *36 | 43-401002-22 | Anvil | (RH-Type 1/2") |
| 15 | 41-401015 | Rotor | | 43-401002-23 | Anvil | (M-Type 1/2") |
| 16 | 41-401016 | Rotor Blade (6) | 37 | 40305 | O-Ring | (6.5x2) |
| 17 | 70117-13 | Spring Pin (2) (2.5) | 5) 38 | 40303 | Retaining Ring | |
| 18 | 41-401018 | Cylinder | 42 | 43-403847 | Valve Spring | |
| 19 | 41-401019 | Front End Plate | 43 | 75-725146 | Valve Stem | |
| 20 | 06801 | Ball Bearing (680 | 1) 44 | 75-725145 | Rubber Spacer | |
| 21 | 41-401021 | Reverse Valve Knob, | 50 | 41-401050 | Muffler Material | |
| 22 | 610225 | Pin (4x15 | 8) 52 | 41-401052 | Plastic Body | |
| 23 | 795846 | Spring | 53 | 41-401053 | Muffler Material | |